

Woodshop Cleaning Checklist

- Sweep and vacuum floors, including under workbenches.
- Wipe down all tools and benches with a microfiber cloth.
- Clean and empty dust collection systems and shop vacs.
- Organize scrap wood and discard unusable pieces.
- Wipe down wall-mounted tool storage and pegboards.
- Empty trash and recycling bins.
- Clean and oil cast iron surfaces (e.g., table saw).
- Check air filters and replace if needed.
- Remove clutter from work surfaces.
- Check fire extinguisher and safety equipment status.